	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Errorpefinition	Er ro rs
1	BRS	L 1	2	20030012693.did.	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/2 4 23:49			0
2	BRS	L 2	1	1 and number\$1	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2004/06/2 5 00:52			0
3	BRS	L 3	128	436/526.ccls. and ((sensor\$1 or detect\$5 or photo\$8) near5 (substrate\$1 or chip\$1 or support\$1))	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/2 5 01:11			0
4	BRS	L 4	0	5922617.pn. and inductance	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2004/06/2 5 01:11			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	ErrorDefinition	Er ro rs
5	BRS	L 5	4	436/526.ccls. and inductance	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2004/06/2 5 01:12			0
6	BRS	L 6	111	ferromagnetic\$6)	JPO;	2004/06/2 5 01:17			0
7	BRS	L 7	147	((magnet\$6 or paramagnetic\$6 or ferromagnetic\$6) near10 (bead\$1 or praticle\$1 or particulate\$1)) and (coil\$1 same inductance)	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2004/06/2 5 01:17			0
8	BRS	8 L	2283 45	436/\$.ccls. or 422/\$.ccls. or 435/\$.ccls.	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2004/06/2 5 01:17			0

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comments	Errorpefinition	Errors
9	BRS	L 9	22	7 and 8	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2004/06/2 5 01:18			0